



# MIDWEST BIODIESEL PRODUCTS, LLC

*Powering the Future*


July 11, 2011

Via Certified U.S. Mail/Return-Receipt Requested

Air and Radiation Division  
United States Environmental Protection Agency  
Region 5  
Ralph Metcalfe Federal Building  
77 West Jackson Boulevard  
Chicago, Illinois 60604

Compliance Section  
Illinois Environmental Protection Agency  
Division of Air Pollution Control  
1021 North Grand Avenue East  
P.O. Box 19276  
Springfield, Illinois 62794-9276

Re: New Source Performance Standards – Semiannual Report  
Period from October 2010 through March 2011  
Midwest Biodiesel Products, LLC  
South Roxana, Illinois



Dear Sir or Madam:

Midwest Biodiesel Products, LLC (Midwest), located in South Roxana, Illinois, is a biodiesel manufacturing facility subject to federal New Source Performance Standard requirements at 40 CFR Part 60, Subparts A and VVa. The purpose of this communication is to provide the semiannual reporting prescribed by 40 CFR §60.487a(c) for the above-referenced period.

Information for the reporting period as prescribed in §60.487a(c) is provided as Table 1. No process unit shutdowns occurred during the reporting period.

I certify that the information contained in this report is true, accurate, and complete.

If you have any questions, please do not hesitate to contact the undersigned at (618) 254-2920.

Respectfully submitted,  
Midwest Biodiesel Products, LLC

Terry L. Zintel  
President

cc: Illinois Environmental Protection Agency  
Division of Air Pollution Control  
2009 Mall Street  
Collinsville, Illinois 62234

**Midwest Biodiesel Products, LLC**  
**South Roxana, Illinois**

**Table 1, Summary of Equipment Leaks and Repairs Per Section 60.487a(c)**

**Reporting Period:** October 2010 through March 2011

<i>Process Unit Identification</i>	<i>No. Valves for Which Leaks Were Detected</i>	<i>No. Valves for Which Leaks Were Not Repaired</i>	<i>No. Pumps for Which Leaks Were Detected</i>	<i>No. Pumps for Which Leaks Were Not Repaired</i>	<i>No. Compressors for Which Leaks were Detected</i>	<i>No. Compressors for Which Leaks Were Not Repaired</i>	<i>No. Connectors for Which Leaks were Detected</i>	<i>No. Connectors for Which Leaks Were Not Repaired</i>
Feedstock	0	0	0	0	0	0	0	0
Methanol	0	0	0	0	0	0	0	0
Methox	0	0	0	0	0	0	0	0
Process Blending	0	0	0	0	0	0	0	0
Reactors	0	0	0	0	0	0	0	0
Centrifuge 1 and 3	0	0	0	0	0	0	0	0
Glycerin Column	0	0	0	0	0	0	0	0
Biodiesel Column	0	0	0	0	0	0	0	0
Settling Tanks	0	0	0	0	0	0	0	0
Water Wash	0	0	0	0	0	0	0	0
Centrifuge 2	0	0	0	0	0	0	0	0
Ionic Resin	0	0	0	0	0	0	0	0
Finished Product	0	0	0	0	0	0	0	0
Vapor Recovery System	0	0	0	0	0	0	0	0
<b>Totals:</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>

**Midwest Biodiesel Products, LLC**  
**South Roxana, Illinois**

**Table 1, Summary of Equipment Per Section 60.487a(b)**

<i>Process Unit Identification</i>	<i>No. Valves in Gas/Vapor and in Light Liquid Service Subject to Section 60.482-7a</i>	<i>No. Pumps in Light Liquid Service Subject to Section 60.482-2a</i>	<i>No. Compressors Subject to Section 60.482-3a</i>	<i>No. Connectors Potentially Subject to Section 60.482-11a</i>
Feedstock	1	0	0	109
Methanol	23	2	0	83
Methox	32	2	0	126
Process Blending	22	0	0	102
Reactors	2	0	0	155
Centrifuge 1 and 3	0	0	0	136
Glycerin Column	2	0	0	143
Biodiesel Column	12	1	0	121
Settling Tanks	0	0	0	115
Water Wash	0	0	0	119
Centrifuge 2	0	0	0	79
Ionic Resin	0	0	0	141
Finished Product	1	0	0	132
Vapor Recovery	0	0	0	28
<b>Totals:</b>	<b>95</b>	<b>5</b>	<b>0</b>	<b>1,589</b>

Notes:

<sup>1/</sup> Facility's program conservatively requires annual monitoring of all connectors, regardless of service type.